D.1.12	Daily	Visible	Emissions	Notations	Per E	ach [Daylight	Shift
			(Stacl	k SDS 04)				

		·	•	
VISIBLE EMISSION NOTA	TIONS			
	Sourcia			
Date of Inspection: 5///	15			
Shift: 1st Shift or 2nd St	lift Ti	me: 5		
Unit	Visual Inspection NORMAL:		Comments	
	OF ABNORMAL			
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

18	300.	
622		
V-street	keca ara	

VISIBLE EMISSION NOTATI	UNS	
Inspector:		
(ed. (conto	
Date of Inspection: 5//	115	
Shift: 1st Shift or 2nd	d Shift Time:	5 pm

Unit	Visual	Comments
And the second of the second o	Inspection	
	<u>NORMAL</u>	
A property of the control of the con	or	
(1) (1) (1) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	<u>ABNORMAL</u>	
Visible Emission From Shaker	No	
Visible Emission From Discharge		·
Conveyor System	Nor	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:	÷	,		
Date of Inspection:				
Shift: 1 st Shift or 2 nd Sh	ift Ti	me:		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nov			
Visible Emission From Discharge Conveyor System	NOGV			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMIS	SION NOTATI	ONS			
Inspector:	Damla	n Salina	, Dr		
Date of Inspecti		-15			
Shift: 1st Sh	ift or 2nd	d Shift	Time:	SIPM	

Unit	Visual	Comments
and the state of t	Inspection	
RESERVE AND CONTRACTOR OF THE PROPERTY OF THE	<u>NORMAL</u>	
And the second of the second o	or	
And the second of the second o	<u>ABNORMAL</u>	
Visible Emission From Shaker	Nov	
Visible Emission From Discharge	7	·
Conveyor System	NH	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015 5 of 6

D.1.12 SDS I Daily Visible	Emission Stations	Per Each Daylight Shift
	(Stack SDS 04)	

VISIBLE EMISSION NOTATIONS

* 1315C	L L.W.13310	11 110 17 11 10 110		
Inspect	or:	Smelko		
Date of	Inspection:	May 3,15		
Shift:	1st Shift	or 2nd Shift	Time: 5200	

Unit.	Visual Inspection <u>NORMAL</u> or ABNORMAL	Comments
Visible Emission From Shaker	NUR	
Visible Emission From Discharge Conveyor System	NOR	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015

D.1.12 SDS I Daily Visible	Emission otations	Per Each	Daylight Shift
	(Stack SDS 04)		

VISIBLE EMISSION NOTATIONS

Inspector: Date of Inspection: Shift: 1st Shift Time:

		210000			
Unit	Visual	10 (PH)	Comme	nts	Approximation and the second con-
	Inspection			g-90 (g-90)	44.21
	<u>NORMAL</u>				
Charles and the second	or			TOTAL CONTRACTOR OF THE PARTY O	
Application of the second seco	<u>ABNORMAL</u>				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge					
Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015

D.1.12 SDS I Daily Visible	Emission. Stations	Per Each Daylight Shift
	(Stack SDS 04)	· ·

VISIBLE	EMISSION	NOTATIONS

Inspector: Smell o

Date of Inspection: May 4/5

Shift: 1st Shift or 2nd Shift Time: 5:00

Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Com	ments	
Visible Emission From Shaker	nor			-	
Visible Emission From Discharge Conveyor System	hoR	Sagenolities			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015 5 of 6

VISIBLE	EMISSION	NOTATIONS

Inspector:

George A Sunding

Date of Inspection:

Shift: 1st Shift or 2nd Shift Time: 5100pm

Unit	Visual Inspection	Comments
$F_{ij} = \{ \begin{array}{ccc} F_{ij} & F_{ij} & F_{ij} \\ F_{ij} & F_{ij} \\ F_{ij} & F_{ij} \\ F_{ij} & F_{ij} & F$	NORMAL	
The second secon	or <u>ABNORMAL</u>	
Visible Emission From Shaker	Wor	
Visible Emission From Discharge Conveyor System	Nor	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 SDS I Daily Visible Emission otations Per Each Da	ylight Shift
(Stack SDS 04)	

VISIBLE EMISSION NOTATIONS

Inspector:

Smello

Date of Inspection:

Shift: 1st Shift or 2nd Shift

Time: 500 Am

		· I			
Unit	Visual		Comments	1. (A)	
Section 1 and 1 an	Inspection				5.0 1.00 (1.
	<u>NORMAL</u>				
	OF				
	<u>ABNORMAL</u>			Establishment Programme Section 1997	English and making the
Visible Emission From Shaker	nor	year one			
Visible Emission From Discharge					
Conveyor System	NOK				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015 5 of 6

Inspector: Time: 5:00 pm

Unit	Visual		Comments	
The state of the s	Inspection	The second secon	gane Region of Arthur Sandan	
The Control of the Co	<u>NORMAL</u>	manifest and a		
	or	places.	and the second s	and the second s
	<u>ABNORMAL</u>			Table 19 Committee of the Committee of t
Visible Emission From Shaker	Nor			
Visible Emission From Discharge	11.0			
Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

5 of 6 Revised 5/1/2015

VISIBLE EMISSION NOTA	TIONS			
Inspector: Paul La	W			
Date of Inspection:	6-15			
Shift: 1st Shift or 2nd Sh	rift Ti	Ime: 5: 66 0m		
Unit	Visual Inspection NORMAL		Comments	
	or <u>ABN</u> ORMAL			
Visible Emission From Shaker	nar	eponent.		
Visible Emission From Discharge Conveyor System	Oov			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:				
Date of Inspection:				
Shift: 1 st Shift or 2 nd Sh	ift Ti	me:		
Unit:	Visual Inspection NORMAL		Comments	
Visible Emission From Shaker	<u>ABN</u> ORMAL			
Visible Emission From Discharge Conveyor System	!			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 SDS I Daily Visible	Emission otations	Per Each	Daylight Shift
	(Stack SDS 04)		

VISIBLE EMISSION NOTATIONS

Inspect	or:		Smelko	
Date of	Inspection:		May 7;1	15
Shift:	1st Shift	or	2nd Shift	Time: 500AM

	_		L		
Unit	Visual	100-100	Comr	nents	
。 1987年 - Angelen Jackson (1997) - Angelen Jackson (1997)	Inspection		regulation and State of the		
	<u>NORMAL</u>				
Approximately and the second	or or	and the second second			
and the second s	<u>ABNORMAL</u>				$A^{*} = A^{*} + 2^{*} A^{*} $
Visible Emission From Shaker	nor				
Visible Emission From Discharge	000				
Conveyor System	VIOR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015 5 of 6

VISIBLE EMISSION NOTA	TIONS			
Inspector:	acren 3 C	175C		
Date of Inspection:	5-7-2	015		
Shift: (1 st Shift) or 2 nd Sh	lift Ti	me: 5		
Unit	Visual Inspection		Comments	
	NORMAL or			
	ABNORMAL			
Visible Emission From Shaker	161	esterment.		
Visible Emission From Discharge Conveyor System	0106	Sterr		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector: Seremy Hi	andini	i	~	
Date of Inspection:	15			
Shift: 1st Shift or 2nd Sh	ift Ti	me: 5,00am		
Unit	Visual Inspection <u>NOR</u> MAL		Comments	
	or <u>ABN</u> ORMAL			
Visible Emission From Shaker	Noc			
Visible Emission From Discharge Conveyor System	NOC			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector: George A	anchez				
Date of Inspection: 5/8/15					
Shift: (1st Shift) or 2nd Shift	Time:	?00pm			
Unit	Visual Inspection <u>NORMAL</u> or		Cor	mments	
approved the company	<u>ABNORMAL</u>				
Visible Emission From Shaker	Non				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015

VISIBLE EMISSION NOTA	ATIONS				
Inspector: Pew Land	V				
Date of Inspection:	9-15				
Shift: (1 st Shift) or 2 nd Si	nift Ti	me: 5:00 pm	-		
Unit	Visual Inspection		Comment	S	
	NORMAL:		i dan di partiti di 1900. Managan di 1900, dan di 1900, da		
	or <u>ABN</u> ORMAL :				
Visible Emission From Shaker	Δ				
i e	1 1000	l .			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Visible Emission From
Discharge Conveyor System

D.1.12 SDS I Daily Visible Emissic Notations Per Each page ...

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS

Inspector: Jame Gan	CIU				
Date of Inspection: 5/10/15					
Shift: 1st Shift or 2nd Shift	t Time:	5 AM			
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL			Comments	
Visible Emission From Shaker	A/BR				
Visible Emission From Discharge Conveyor System	NóR		•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

١.	ISIBL	F	F١	ΛIG	: <	\square	IN	\cap	ΓΔΤ	Γ	N	:
v	וסוכוי	-Г-		/113	3.3	יוטו	וו נ		ıA	ווו	uv.)

Inspector:) aime NC	CRC19			
Date of Inspection:				
Shift: 1st Shift or 2nd Shif	t Time:	5AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Non	The improvement of the second		
Visible Emission From Discharge Conveyor System	Non	Employee.		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Nor

VISIBLE EMISSION NOTATIONS

TIGIBLE ENTIROTOTION TO TAXABLE			_	
Inspector: George A Su	anetier			
Date of Inspection: 5/11/15)			
Shift: 1st Shift or 2nd Shif	ft Time:	5:00 pn		
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	Wor			
Visible Emission From Discharge				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System

D.1.12 SDS I Daily Visible Emission Stations Per Each Daylight Shift

(Stack SDS 04)

V	1	S	IB	LE	E	VI	IS	SI	0	N	Ν	O	T.	A7	1	ΟI	N	S
---	---	---	----	----	---	----	----	----	---	---	---	---	----	----	---	----	---	---

1	or: 3m				
Date of	Inspection:	Ma	y 13, 15		
Shift:	1st Shift	or	2nd Shift	Time:	٦

Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL	Comments
Visible Emission From Shaker	nog	
Visible Emission From Discharge Conveyor System	nor	· · · · · · · · · · · · · · · · · · ·

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS

Inspector: Smelko					
Date of Inspection: May 13	-				
Shift: 1st Shift or 2nd Shift	Time:	5:00			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Com	oments	
Visible Emission From Shaker	noR	, menta			
Visible Emission From Discharge Conveyor System	nor.	,			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.


VISIBLE EMISSION NOTATIONS

Inspector: George A	Sancher				
Date of Inspection: 5/13/					
Shift: 1st Shift or 2nd Shift	t Time:	5:00 pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Co	omments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	1201				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



Non





(Stack SDS 04)

Visible Emission From Discharge

Conveyor System

Inspector: Jame N Go	M2C(C)			
Date of Inspection: 5/14/15				
Shift: 1st Shift or 2nd Shif	t Time:	5Am		
Unit.	Visual Inspection <u>NORMAL</u> or		Comments	
Visible Emission From Shaker	ABNORMAL			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



Visible Emission From Discharge

Conveyor System

Nor

Inspector: George A. San	her			
Date of Inspection: 5/14/15				
Shift: 1st Shift or 2nd Shift	ft Time:	5:00 pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	· War			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

|--|

VISIBLE EMISSION NOTATIONS

Inspector: AMP N (6)				
Date of Inspection: 5/15/15				
Shift: 1st Shift of 2nd Shif	t Time:	5Am		
Unit.	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector: Beorge A S	ancher				
Date of Inspection: 5//3-//3	S				
Shift: 1st Shift or 2nd Shi	ft Time:	5200pm			
Unitig	Vision (Comments		
	LEVENSICE CONTRACTOR				
	OI ABICIORIMAL				
Visible Emission From Shaker	Nor	Contract the second		Maridian out of the control of the c	
Visible Emission From Discharge	Noc				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







(Stack SDS 04)


VISIBLE EMISSION NOTATIONS

Inspector: Darren T	3 and TOE			
Date of Inspection:				
Shift: 1st Shift or 2nd Shif	t Time:	500		
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Noc	u.		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS			
Inspector:	emy Hardin			
Date of Inspection:	5/17/15			
Shift: 1 st Shift or 2 nd Sh	Time	500 am		
Unit (1997)	Visual Inspection NORMAL		Comments	
	or <u>ABN</u> ORMAL			
Visible Emission From Shaker	Normal			
Visible Emission From Discharge Conveyor System	NOrmal			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EN	IISSION	NOTA	TIONS
Inchactore		against an	

Inspector:	Darra	3 androe	
Date of Inspection:	5-	17-2015	
Shift: 1st-Shift	or 2nd Shift	Time:	5100

unit	Visual	Comments
and the second s	Inspection	
John British School President Co.	<u>NORMAL</u>	
The second secon	or or	
	<u>ABNORMAL</u>	
Visible Emission From Shaker	Nor	
Visible Emission From Discharge		·
Conveyor System	Nor	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	_		_		
Inspector:	emy Hardin	•			
Date of Inspection: 5/18	(15)				
Shift: 1st Shift or 2nd Shift	Time:	Socam	}		
lúmic	Vistal I hispestini <u>Normal</u> Or ABNormal			ommensal	
Visible Emission From Shaker	vorma!				
Visible Emission From Discharge Conveyor System	Normay				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			· -			
Inspector: Smelfo					,	
Date of Inspection: May 18	,15					
Shift: 1st Shift or 2nd Shift	t Time:	520pm				
Unit	Vizibēl Habi estirani <u>INORIMANI</u> Oj			Gomments !		
Visible Emission From Shaker	MABNORMAL.					
Visible Emission From Discharge Conveyor System	nor	2008/200-		,		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS

Inspector: Smelko					
Date of Inspection: May 19	.15				
Shift: 1st Shift or 2nd Shif	t Time:	5:00 pm	- -		
блике	Villural Vintanie adjanni		. i	olganategit (E)	
	<u>Mormal</u>				
	ALEINOTRIVIAL				
Visible Emission From Shaker	nor	· Procedures			
Visible Emission From Discharge Conveyor System	noa	, Allenane,			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			 ,		
Inspector: George A. Sa.	nchor				
Date of Inspection: 5/28/15					
Shift: 1st Shift or 2nd Shift	Time:	3:00 pm			
Onit.	Vigoral แปลยุกยะทำจัดใ			Communis	
	TOM TOM ABMORIMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS			_		
Inspector: Smellso					
Date of Inspection: May 20	,15				
Shift: 1st Shift or 2nd Shift	Time: ¬	5:00 pm			
topite	Visibeli Hrispeadian		r i jagorini Propinsi	nedus	
	<u>เพื่อเริ่มพิพิปั</u>				
	ABNORMAL				
Visible Emission From Shaker	nor	-2000-games			
Visible Emission From Discharge	Mayo				
Conveyor System	IIOR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			_		
Inspector: Crange A San	chez				
Date of Inspection: 5/21/15	· .]		
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm	<u></u>		
Wpffc	Vistell (-]lispestion <u>Norwyll</u> or ABNORWAL			ninienis	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS							
Inspector: SmeWG							
Date of Inspection: May 2)	15						
Shift: 1st Shift or 2nd Shift	Time:	500 PM	-	. •			
Unition (1) Unitio	Victel The prestion The prestion The prestion The prestion of the prestion				Comments		
Visible Emission From Discharge Conveyor System	nor nor	_				<u> </u>	


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: Creeke A So	inehez			
Date of Inspection: 5/22/1	5			
Shift: 1st Shift or 2nd Shi	t Time:	5:00 Am		
(Drift)	Victorii ! .		Comments:	
	<u>NORMAL</u>			
	OI ALEINIARIANAL			
Visible Emission From Shaker	Nor			
Visible Emission From Discharge	Nar			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: Smell 6				
Date of Inspection: May 22	いけか			
Shift: 1st Shift or 2nd Shift	Time:	500		
Unit	Victoral Chrispestiani		Comments	
	101 ABNORMAL			
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS					
Inspector: Creorge A San	cher				
Date of Inspection: 5/23/15					
Shift: 1st Shift or 2nd Shif	Time:	5:00An			
Unit	VISI0ēI Nokspi≥ia Troloi		ologrami Haldings 178	Marie	
	INGRIMAL				
	ABNORWAL.				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge			•		
Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: Darren 1	3 Cudroe			
Date of Inspection:	3-2015			
Shift: 1st Shift or 2nd Shift	t Time:	7:0p.~		
(Initia	Visiofal เป็นสติยะเก็บกับ		community of the commun	
	<u>NYORWAL</u> 607			
e sala di	ABINORUVAL.		4	Canada Caraca Carac
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Noc	- Section 1		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector: Alex Bantis	Le				
Date of Inspection: 5/2-4/17					
Shift: 1st Shift or 2nd Shif	t Time:	Im	<u> </u>		
. White	Victori - ได้ยังครับกัด เดอสังได้เป			immients) (7) jainus	
	LOF MBNORMAL				
Visible Emission From Shaker	Nor		`		
Visible Emission From Discharge			•	· ·	
Conveyor System	Nove	Name and described the supplementary of the supplem	panetro e		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	j				
Inspector: Ted Coyn	tor				
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	t Time:	5Am			
Unit	Visual			omments.	
	<u>INORMAL</u>				
	or Abnormal				
Visible Emission From Shaker	No				
Visible Emission From Discharge	,)		The state of the s	•	
Conveyor System	l No/	On the character of the control of t			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.


VISIBLE	FMISSION	NOTATIONS


Inspector: Granze A. Sun Date of Inspection: 5/25/45	chez			
Date of Inspection: 5/25/65				
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm	_	
(Unite:	Vindo-all			Olumiano.
	<u>INDEMIAL</u>			
	Or A <u>BNORDAV</u> AS			
Visible Emission From Shaker	Nor		EXTENSION AND STOCKED OF PERSON FOR STANSON AND STANSON AND STANSON AND STANSON AND STANSON AND STANSON AND ST	CO TOTAL CONTRACTOR SECTION STATES
Visible Emission From Discharge Conveyor System	Noc		•	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS		All Land		
Inspector: Smell O				
Date of Inspection: Way 26	,15			
Shift: Ast Shift or 2nd Shift	Time:	500AM		
Onic .	Vijetjel Lunepeedfont Lunepeedfont		omments	
	oji Mentornavale			
Visible Emission From Shaker	NOR	and the same of th		
Visible Emission From Discharge Conveyor System	nor	_		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EIVIISSION NOTATIONS			-			
Inspector: Grave A San	choc					
Date of Inspection: 5/26/15						
Shift: 1st Shift or 2nd Shif	t Time:	5:00pm				
Unite	ir i Visibali Modusenendi Modulensia Modulensia			Commonis (II)		
	or Mentorial				i de la companya de La companya de la co	
Visible Emission From Shaker	Nor					
Visible Emission From Discharge Conveyor System	Nor Nor					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	MOCD - 485		····		
Inspector: Smello					
Date of Inspection: Way 27	,15				
Shift: 1st Shift or 2nd Shift	Time:	500			_
Unità	Man Visidiali Mangerationi			oinninienista	
	<u>INDRMAL</u>				
	A ABINORIALE				
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	nor	_			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: Darren ?	3 and Toe			
	27-2015			·
Shift: 1st Shift or 2nd Shift	Time:	6:06		
(Onit.	Visual Visipection Minorimal Of ABINORIMAL		Comments a	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor	, and the second		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			-		
Inspector: Smelke					
Date of Inspection: May 29	, ,))				·
Shift: 1st Shift or 2nd Shift	Time:	500AM			
Unite	บบ Vjistirii - ปุเกษากับกับกับ			Comments	
Page 1	<u>Mornwall</u> Or				
Visible Emission From Shaker	nof			Lunia Landa de la companya de la co	
Visible Emission From Discharge Conveyor System	nor		•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			- .		
Date of Inspection: 5/28/15	her	·			
Date of inspection: 5/28/15					
Shift: 1st Shift or 2nd Shif	t Time:	5:00 pm]		
Unitic	in Visibell Hisperijan		, 14, 17, 166 10, 18, 18, 18, 18, 18, 18, 18, 18, 18, 18	ininjudis	
	<u>inormal</u>				
en e	ABNORWAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	Noc			·	
Conveyor System	1001	1			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			1		
Inspector: Time N Go	ORCIG		_		
Date of Inspection: 5/J9/50					
Shift: 1st Shift or 2nd Shif	t Time:	5AM			
Willia	Victorii Historiationi		Gol	aniento	
	NORMAL				
	ABNORMAL				
Visible Emission From Shaker	NOC	The state of the s			
Visible Emission From Discharge Conveyor System	Non				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EIVISSION NOTATIONS			_		
Inspector: George A Sa	noher	·			
Date of Inspection: 5/29/18					
Shift: 1st Shift or 2nd Shif	t Time:	5pm			
Unit	Victori Nasio∈otioni			ininienis	
	<u>INORIMAL</u>				
	ABINORMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	. 2			•	
Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Sallings Tr				·
a 15				
Time:	5:00AM			
vistal			<u> </u>	
TANMINE TELEVISION IN THE PLEASE TO THE PLE	A Company			
ioji Astriopologi				
Nan				PERSONANT PARPENTUNG TERMINA
	Salings Tr 0-15 t) Time:	Sallings Dr On 15 Time: 5 WAM	Salings Dr On 15 Time: SixAn	Salings Dr On 15 Time: 5:00 Am

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Visible Emission From Discharge

Conveyor System

Nor

VISIBLE EMISSION NOTATIONS					
Inspector:					
Date of Inspection:		1		· .	
Shift: 1st Shift or 2nd Shift	Time:	-			
(Unite	vista Vistal V		o inninatantisi		
	Hnspleations <u>Normal</u>				
	en. Mennornomal				
Visible Emission From Shaker	1 bro		3 200 00 00 00 00 00 00 00 00 00 00 00 00		
Visible Emission From Discharge	Nom	•			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.